

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații  
Automatizări / Materiale Electrice

## Rezistentă 3000W 230V 355x75mm flansa 51x28mm #3355313

Fara TVA: 336,13 Lei

Pret cu TVA: 399,99Lei

Rezistentă 3000W 230V 355x75mm flansa 51x28mm #3355313

immersed length 355mm - width 75mm

flange 51x28 mm

Compatibil cu:

ALPENINOX 0L1870

ALPENINOX 048491

ATEL 27LS015

ELECTROLUX PROFESSIONAL 0L1870

ELECTROLUX PROFESSIONAL 048491

EPMS 1501133

EPMS

GEV 416132

IRCA 1GEL5F093001

IRCA 1GEL5U201002

WHIRLPOOL 771985010907

WHIRLPOOL 148491

ZANUSSI 554048491

ZANUSSI 71048491

ZANUSSI 0L1870

ZANUSSI 048491

ZANUSSI 0617610002

ZANUSSI 0617631800

ZANUSSI 1GEL5U201002

ZANUSSI Dishwasher LU7PDP (503020), LU7ADP (503021), LU7ADPWS (503022), WTU40PDP (503023), WTU40ADP (503024), WTU40ADPWS (503025), WTU40ADPDG (503026), ET7ADP (698019), LU700PDP (698033), LU700ADP (698034), LU700ADPWS (698037)

ZANUSSI Dishwasher hood type LS10D (504000), LS10 (504001), LS10UKRP (504002), LC100 (504003), ECOTEMP12- (504004), LS10/60 (504005), LS10/1 (504006), LS10/12KW (504007), LS10F (504008), LS10DEK (504009), LS10/1UKRP (504010), LS10SW (504011), LS10/50J (504012), LS10/60J (504013), LS10DP (504014), LS10/HD (504015), LS10/UK1 (504018), LS10/UK3 (504019), LS12D (504020), LS12 (504021), LS12UK/RP (504022), LC120 (504023), LS12DP (504024), LS12/60 (504025), LS12F (504028), LS12DEK (504029), LS12HD (504053), LS12/UK3 (504061), ECOTEMP12SW (504063), ECOTEMP12INS (504065), LS12MEX (504078), LS10N (504080), LS14EA (504101), ET12E (504104), LS14EAI (504110), LS14EAI/AU (504116), LS14EA/60 (504117),

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații  
Automatizări / Materiale Electrice

LS14EAASIA (504131), LS14EA/G (504133), LS10EA (504142), LS14EAI/DD (504155), WT65E (504156), WT65EB (504157), WT65EI (504158), ECOTEMP12S (504165), WT65EBI (504166), WT65EBIA (504167), WT65EIA (504168), WT65E60 (504169), WT65EB60 (504170), WT65EBIDG (504173), WT65EBASIA (504174), WT65EIM50 (504175), WT65EIM60 (504176), LS14EADP/G (504179), WT65MED (504180), WT65EJ50 (504183), WT65EJ60 (504186), LS14EAWS (504209), LS14ADPWSG (504210), LS14EAIWS (504211), WT65EBWS (504212), WT65BIDWSG (504213), WT65EBIWS (504214), WT65MEDWS (504215), ET12EWS (504218), WT65ROW (504219), LS14ROW (504220), LS14SANA (504221), WT65EBID (504222), WT65EBIWS (504223), LS14ROW60 (504224), WT65ROW60 (504225), EHTA (504226), EHTA60 (504227), EHTAWS (504228), EHTAI (504229), EHTAID (504230), EHTAIWS (504231), EHTAIDWS (504232), EHTAIG (504233), EHTAIWSG (504234), EHTAIAU (504235), EHTAIMLAU (504236), ZHTAWS (504237), ZHTAID (504238), ZHTAIWS (504239), ZHTAIAU (504240), ZHTA (504241), ZHTA60 (504242), ZHTAI (504243), EHTAIUSPH5 (504244), EHTAIUSPH6 (504245), LS9P (505022), LS9PDD (505033), LS9AUK/3 (505034), LS9P60 (505035), WT55P (505038), WT55P60 (505039), WT55AUK/3 (505040), LS9ADG1 (505041), WT55ADG1 (505042), LS9PAUS (505043), WT55PM50 (505044), WT55PM60 (505045), H2500 (698008), H3500 (698009), HT1200WS (698012), HT1200IWS (698013), H1510SANA (698017), LV1200IWS (698018), HT1200elm (698020), HT1000elm (698021), HT900 (698022), LV900P (698023), LD900 (698024), HT900ADG1 (698028), HT1200BIDG (698029), HT1200BIDW (698038), HT1200 (698050), HT1000 (698051), HT1200INS (698053), ET12EIG (698056), ET12EI (698057), LV1000 (698059), LV1200INS (698060), ET12EICWG (698061), ET12EICW (698062), ET12EIWS (698063), ET12EIF (698065), ET12AI (698097), ET12AIT (698098), AHTAWS (698115), AHTAIWS (698116), AHTAIG (698117), AHTAIWSG (698118), AHTA (698119), AHTAI (698120), HYDRA1200 (727020), HYDRA1000 (727021)

