

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații  
Automatizări / Materiale Electrice

## Magnetron echivalente

Fara TVA: 0,00 Lei

Pret cu TVA: 0,00Lei

LG: 2M219J, 2M214-01GKHLG, 2M213-01GKH, 2M226-01, M246-050GF (2M246-01GKH), 2M246050GF, 2M217J,  
2M24FB-610A, 2M24FA-410A, 2M218-JF, 2M219J;

Samsung: OM75S (71), OM52S61;

Daewoo: 2M254J, 2M248J, 2M218JF;

Witol: 2M219K;

Samsung: OM75S, OM75P;

LG: 2M214-240GP, 6324W1A004A, 6324W1A004B, 2M219K;

Gorenje: 264484;

Toshiba: 2M253K (JT);

Witol: 2M219K;

Samsung OM75S, OM75P;

Panasonic: 2M210-M1;

LG: 2M226-15GKH, 6324W1A004B, 2M214-240GP;

Galanz: M24FB-210A;

LG: 2M214-01GKHLG, 2M226-15GKH, M246-050GF, 2M226-01, 2M213-01GKH;

Daewoo: 2M218 JF;

Galanz: 2M24FA-410A, 2M24FB-610A;

Samsung: OM52S61, OM75S;

Witol: 2M219J; 2M217J

LG: 2M214-01GKHLG, 2M213-01GKH, 2M226-01, M246-050GF (2M246-01GKH), 2M246 050GF, 2M217J,  
2M214-21GKH;

Witol: OM75S (71), OM52S61, 2M24FB-610A, 2M24FA-410A, 2M218-JF, 2M219J;

Daewoo: 2M254J, 2M248J, 2M218JF;

LG: 2M214-01GKHLG, 2M226-15GKH, M246-050GF, 2M226-01, 2M213-01GKH;

Daewoo: 2M218 JF;

Galanz: 2M24FA-410A, 2M24FB-610A;

Samsung: OM52S61, OM75S, OM75P31;

Witol: 2M219J;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP;

Galanz: M24FB-210B, 2M24FA-410A;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M213-GKH;

Galanz: M24FB-210B, 2M24FA-410A;

magazin online HORECA

**Piese schimb / Accesorii / Consumabile / Reparații**  
**Automatizări / Materiale Electrice**

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M213-GKH;

Galanz: M24FB-210B, 2M24FA-410A;

Daewoo: 2M218 HF;

Samsung: OM75S, OM75P;

Galanz: M24FB-210B, 2M24FA-410A, M24FB-210A;

Toshiba: 2M231H (JT) 1;

Daewoo: 2M218H-M, 2M219;

Panasonic: 2M261-M32 (invertor), 2M210-M1, 2M236-M42 (invertor);

Toshiba: 2M253K (JT);

Witol: 2M219K;

Samsung: OM75S, OM75P, OM75S (10);

Galanz: M24FB-210A;

Panasonic: 2M210-M1, 2M261-M22 (invertor);

LG: 2M226-35GKH, 2M226-15GKH;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M261-M32, 2M286-23GKH;

Galanz: M24FB-210B, 2M24FA-410A;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M261-M32, 2M286-23GKH, 2M809-15GKH;

Galanz: M24FB-210B, 2M24FA-410A;

Panasonic: 2M286-23GKH, 2M236-M62J1Y, 2M261-M32;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M261-M32, 2M286-23GKH;

Galanz: M24FB-210B, Galanz 2M24FA-410A;

Panasonic: 2M286-23GKH, 2M236-M62J1Y, 2M261-M32;

Daewoo: 2M218 HF;

LG: 2M213-21GKH, 2M282H, 2M211A-M2, 2M214 240GP, 2M261-M32, 2M286-23GKH

Galanz: M24FB-210B, 2M24FA-410A;

