

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

Rezistența cuptor 1200W 230V 365x315mm flansa 70x22mm #D355006

Fara TVA: 252,10 Lei

Pret cu TVA: 300,00Lei

Rezistența cuptor 1200W 230V 365x315mm flansa 70x22mm #D355006

1200W 230V - distance between the holes 56mm

length 365 - width 315/85mm

bracket 320mm - flange 70x22mm

Compatibil cu:

ELECTROLUX 50170990001

ELECTROLUX 3581907387

ELECTROLUX 3570076012

ELECTROLUX 3570076038

EPMS 3570076038

ELECTROLUX Kitchen C2645 (94770010300), CF2640S (94770010400), CFX6647 (94770011700), DEM6640SA (94771006700), XEM6640SA (94771006800), TP466EA (94771007000), DEM660SA (94771007300), XEM660SA (94771007400), PR660M (94771007500), PR660WE (94771007600), PR660XM (94771008000), BE6631A (94772001400), BE661A (94772001600), XE5540SA (94773004100), XE5540A (94773005000), PR550XE (94773005100), XEM6540SA (94773005200), EK6721X (94773005400), CVX6647 (94773005700), P6AMTX (94773005900), R5XAE (94773006000), R6XSM (94773006200), R60XSE (94773006300), R66XSM (94773006400), P6AMTX (94773006600), Z66XES (94773007000), P56AMTX (94773007100), CMX6540SA (94773007200), CMX6640SA (94773007300), R5XAE (94773008100), PSX56AMT (94773008400), R6XSM (94773008600), R60XSE (94773008700), Z66XES (94773008900), Z66XES (94773008902), CMX6540SA (94773009000), CMX6540SA (94773009001), PSX6AMT (94773009100), PX6AMT (94773009300), R66XSM (94773009500), EK6721XL (94773009900), CMX6640SA (94773010000), Z65XES (94773010700), Z65XES (94773010701), Z65XES (94773010702), Z66XMS (94773010800), Z66XMS (94773010801), Z66XMS (94773010802), R6XAE (94773011000), R66XAE (94773011200), RX5ESA (94773013700), RX5ESA (94773013701), RX6ESA (94773013800), RX6ESA (94773013801), RX6MSA (94773014100), RX6MSA (94773014101), RX66MSA (94773014300), RX66MSA (94773014301), PX65AMS (94773017500), PX66AMS (94773017700), PXP66AMS (94773017800), DE6540A (94774009600), PR560WE (94774011400), C2040 (94774012100), C2506 (94774012200), DE650A (94774013500), CV2504S (94774013700), M560E (94774014000), PR560WE (94774015100), PR660WM (94774015700), EK6720 (94774016100), EK6722 (94774016400), C2050 (94774016900), CV2505SE (94774017200), CV2640SE (94774017400), P5AE (94774018000), P56AE (94774018300), P56AMT (94774018400), P6AE (94774018700), P6AM (94774018800),



magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

R6BAE (94774019500), R66BSM (94774020000), P56AMT (94774020400), Z66BES (94774022600), P6AMTL (94774023500), CE5540A (94774023900), CMN6540SA (94774024300), CMN6640SA (94774024600), R66BAE (94774025400), P5E (94774026500), CE5540A (94774027800), PW56AE (94774028500), PW56AMT (94774028700), R6BAE (94774029000), Z66BES (94774029400), Z66BES (94774029401), Z66BES (94774029402), CMN6540SA (94774029800), EK6720 (94774030000), PW6AM (94774030400), PW6AMT (94774030600), R66BAE (94774030900), R66BSM (94774031000), EK6722 (94774032000), CMN6640SA (94774032300), CMN6640SA (94774032302), R5E (94774044700), R5ES (94774044900), R6ES (94774045100), RB6ESA (94774045200), RB6ESA (94774045201), RB5ESA (94774045300), RB5ESA (94774045301), RB6MSA (94774045500), RB6MSA (94774045501), R66EA (94774045600), R66EA (94774045601), RBX66MSA (94774046300), RBX66MSA (94774046301), R6E (94774046400), P55E (94774050800), P55E (94774050801), P65AES (94774051200), P66AES (94774051400), P55AES (94774051600), P55AES (94774051601), PW65AMS (94774051900), PW66AMS (94774052100), RB55E (94774057900), RB55ES (94774058100), RBP55ESA (94774058300), P05E (94774061300), P5AES (94774061500), BL65 (94775002600), BL66 (94775002700), BR66 (94775002800), PNP66AMS (94775006100), PNR66AMS (94775006200), DE6531 (94776002100), M560E (94776002200), C2013 (94776002400), TP406EA (94776002500), PR561WE (94776002600), DE6531A (94776002800), PR561WE (94776002900), C2507 (94776003000), P561E (94776003100), R61BAE (94776003500), CE6531A (94776004400), PW561E (94776005500), R61BAE (94776005600), CE6531A (94776006000), R61ES (94776009400), EK6725 (94776009500), ZC661CM (94776009800), RX9ESA (94777004800), RX9ESA (94777004801), PX955AMS (94777005200), PX955AMS (94777005201), PX955AMS (94777005202), RX952MSA (94777005500), RX952MSA (94777005501), RX952MSA (94777005502), FRX953MSA (94777005600), RX953MSA (94777005601), RX953MSA (94777005602), RB910E (94777006900), RB900ES (94777007300), RB920MSA (94777007500), RB930MSA (94777007600), RX920MSA (94777007800), RX930MSA (94777007900), PX955AMS (94777008200), PX955AMS (94777008201), RB900ES (94777009300), RB900ES (94777009301), RB920MSA (94777009500), RB920MSA (94777009501), RX920MSA (94777009700), RX920MSA (94777009701), RX930MSA (94777009800), RX930MSA (94777009801), P955AES (94777010200), P955AES (94777010201), PC952E (94777010400), PC952E (94777010401), P951E (94777011000), P951E (94777011001), P951AES (94777011100), P951AES (94777011101), PW952AMS (94777011200), PW952AMS (94777011201), XE9541SA (94778002500), XEM9542SA (94778002600), XEM9542SA (94778002900), PR592XE (94778003000), CVX6947 (94778003300), EK9720X (94778003400), CVX6947 (94778003500), P92AEX (94778003600), R92XSM (94778003700), R901XSE (94778003800), P92AEX (94778003900), Z96XES (94778004000), CMX9542SA (94778004100), P92AEX (94778004300), P92AEX (94778004301), CMX9542SA (94778004400), CMX9542SA (94778004401), EK9720X (94778004500), R922XSM (94778004600), Z96XES (94778004900), Z952XES (94778005000), Z952XES (94778005001), Z952XES (94778005002), RX92ESA (94778005500), RX92ESA (94778005501), RX92MSA (94778005600), RX92MSA (94778005601), DE9550A (94779007700), DE9550A (94779009500), PR590M (94779010000), PR590WM (94779011600), R99AE (94779012900), R99AE (94779014300), R9ES (94779016000), R9ES (94779016001), RB9ESA (94779016200), RB9ESA (94779016201), R9PE (94779016300), R9PE (94779016301), R9PE (94779016302), P955AES (94779017200), P955AES (94779017201), P955AES (94779017202), RB951E (94779017700), RB951E

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

(94779017701), RB951E (94779017702), RB95ES (94779017900), RB95ES (94779017901), RB95ES (94779017902), RB952MSA (94779018200), RB952MSA (94779018201), RB952MSA (94779018202), RB953MSA (94779018300), RB953MSA (94779018301), RB953MSA (94779018302), DE9541 (94781007300), DE9542 (94781007400), C2942 (94781008100), PR591WE (94781008300), CV2948 (94781008700), DE9541A (94781009000), DE9542A (94781009100), DEM9542SA (94781009200), PR592ES (94781009400), PR591WE (94781009600), C2943 (94781009800), PR592WES (94781010200), EK9721 (94781010300), C2940 (94781010400), CV2950S (94781010600), P91E (94781010800), P92AE (94781010900), P92AMT (94781011000), R91BAE (94781011200), R92BAE (94781011300), R92BSM (94781011400), P92AMT (94781011600), CE9541A (94781012100), CM9542SA (94781012300), P91E (94781012800), P91E (94781012801), P92AE (94781012900), P92AE (94781012901), P92AMT (94781013000), P92AMT (94781013001), CE9541A (94781013100), CE9541A (94781013101), CM9542SA (94781013300), R91BAE (94781013500), R92BAE (94781013600), R92BSM (94781013700), EK9721 (94781014500), Z952BEA (94781014600), R92E (94781014700), R91E (94781014900), R92ES (94781015000), R92E (94781015200), RB92ESA (94781015300), RB92MSA (94781015400), P951E (94781015700), P951E (94781015702), P951AES (94781015800), P951AES (94781015801), P951AES (94781015802), PW952AMS (94781015900), PW952AMS (94781015901), PW952AMS (94781015902), CB2942 (94782001100), P92CE (94782001200), R92CAE (94782001400), CEB9542A (94782001500), P92CE (94782001700), P92CE (94782001701), CEB9542E (94782001800), R92CAE (94782002000), RC92EA (94782002200), CE9542S (94783002000), CE9542SA (94783002300), PR592CE (94783002400), CB6942 (94783002600), CE9542A (94783003000), Z951CE (94783003100), PC952E (94783003200), PC952E (94783003202)

ELECTROLUX Kitchen gas P660M (94771004600)

