

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

Valva alimentare 1/2" teava ø18mm 230mm #514269

Fara TVA: 529,41 Lei

Pret cu TVA: 630,00Lei

Valva alimentare 1/2" teava ø18mm 230mm #514269

racord 1/2" FE

diametru de teava 18mm

orificiu de scurgere 100mm

înaltime totala 230mm

înaltime de scurgere 140mm

unghi de rotatie 360°

Compatibil cu:

ASCASO CZA749

BARON 41826900260, BN826900260

COOKMAX 826900260

ELECTROLUX CZA749

EPMS CZA749

WHIRLPOOL 0502173

ZANUSSI 0502173

ALPENINOX

ASCASO

BARON SERIE700

COOKMAX 137001, 137002, 137003, 137004, 137201, 137202

ZANUSSI Bratt Pan ABR/E800 (221517), ABR/E800 (221564), ABR/E800UK (221533), ABR/E800UK (221571), ABR/E801 (221519), ABR/E805 (221518), ABR/E805 (221565), ABR/E806 (221520), ABR/E810 (221521), ABR/E810 (221566), ABR/E811 (221523), ABR/E811 (221568), ABR/E815 (221522), ABR/E815 (221567), ABR/E816 (221524), ABR/E816 (221569), ABR/G800 (221501), ABR/G800 (221558), ABR/G800D (221509), ABR/G801 (221503), ABR/G801D (221511), ABR/G805 (221502), ABR/G805 (221559), ABR/G805D (221510), ABR/G805NL (221526), ABR/G806 (221504), ABR/G806D (221512), ABR/G810 (221505), ABR/G810 (221560), ABR/G810D (221513), ABR/G811 (221507), ABR/G811 (221562), ABR/G811D (221515), ABR/G815 (221506), ABR/G815 (221561), ABR/G815D (221514), ABR/G816 (221508), ABR/G816 (221563), ABR/G816D (221516), BR/E806 (211520), HBR/E800 (201517), HBR/E800 (201564), HBR/E800 (211517), HBR/E800UK (201533), HBR/E800UK (201571), HBR/E801 (201519), HBR/E805 (201518), HBR/E805 (201565), HBR/E806 (201520), HBR/E810 (201521), HBR/E810 (201566), HBR/E811 (201523), HBR/E811 (201568), HBR/E815 (201522), HBR/E815 (201567), HBR/E816 (201524), HBR/E816 (201569), HBR/G800 (201501), HBR/G800 (201558), HBR/G800D (201509), HBR/G800NL (201525), HBR/G800UK (201532), HBR/G800UK (201570), HBR/G801 (201503), HBR/G801D (201511), HBR/G805 (201502), HBR/G805 (201559), HBR/G805D (201510), HBR/G805NL

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

(201526), HBR/G806 (201504), HBR/G806D (201512), HBR/G810 (201505), HBR/G810 (201560), HBR/G810D (201513), HBR/G810NL (201527), HBR/G811 (201507), HBR/G811 (201562), HBR/G811D (201515), HBR/G815 (201506), HBR/G815 (201561), HBR/G815D (201514), HBR/G816 (201508), HBR/G816 (201563), HBR/G816D (201516), OBR/E800UK (221576), OBR/G800UK (221575), ZBR/E800 (211564), ZBR/E800UK (211533), ZBR/E800UK (211571), ZBR/E805 (211518), ZBR/E805 (211565), ZBR/E810 (211521), ZBR/E810 (211566), ZBR/E811 (211523), ZBR/E811 (211568), ZBR/E815 (211522), ZBR/E815 (211567), ZBR/E816 (211524), ZBR/E816 (211569), ZBR/G800 (211501), ZBR/G800 (211558), ZBR/G800D (211509), ZBR/G800UK (211532), ZBR/G800UK (211570), ZBR/G801 (211503), ZBR/G801D (211511), ZBR/G805 (211502), ZBR/G805 (211559), ZBR/G805D (211510), ZBR/G806 (211504), ZBR/G806D (211512), ZBR/G810 (211505), ZBR/G810 (211560), ZBR/G810D (211513), ZBR/G811 (211507), ZBR/G811 (211562), ZBR/G811D (211515), ZBR/G815 (211506), ZBR/G815 (211561), ZBR/G815D (211514), ZBR/G816 (211508), ZBR/G816 (211563), ZBR/G816D (211516)
ZANUSSI Fry Top ZR/G413 (211519)

