

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

Comutator 0-1 pozitii EGO 4202900003 #2101575

Fara TVA: 42,02 Lei

Pret cu TVA: 50,00Lei

Comutator 0-1 pozitii EGO 4202900003 #2101575

Curent maxim comutat: 16A

Tensiune alimentare: 250V

Temperatura maxima de lucru: 150°C

Ax in forma de D: \varnothing 6x4. \varnothing 6 mm

Compatibil cu:

ALPENINOX

ELECTROLUX PROFESSIONAL

ZANUSSI

EGO 4202900003

ZANUSSI Boiling pan 7550-5.KES40 (615357), 7551-5.KES60 (615358), 7552-5.KES80 (615359), 7553-5.KES100 (615360), 7554-5.KES150 (615361), 7561-3.KES60.RW (615375), 7562-3.KES80.RW (615376), 7563-3.KES100.RW (615377), 7564-3.KES150.RW (615378), 7581-5.KK60 (615456), 7582-5.KK80 (615457), 7583-5.KK100 (615458), 7574-5.KES150 (615476), 7575-5.KES250 (615477), 7750-5.KES40 (616095), 7751-5.KES60 (616096), 7752-5.KES80 (616097), 7753-5.KES100 (616098), 7754-5.KES150 (616099), 7781-5.KK60 (616102), 7782-5.KK80 (616103), 7783-5.KK100 (616115), 7576-5.KES300 (616310), 7573-5.KES100 (616311), 7580-5.KK40 (616577), 7584-5.KK150 (616578), 7780-5.KK40 (616580), 7751-3/85.KES60 (617115), 7550-3/85.KES40.(N) (617204), 7551-3/85.KES60 (617205), 7552-3/85.KES80.(N) (617206), 7553-3/85.KES100.(N) (617207), 7554-3/85.KES150.(N) (617208), 7550-3/90.KES40.(N) (617209), 7551-3/90.KES60 (617210), 7552-3/90.KES80.(N) (617211), 7553-3/90.KES100.(N) (617212), 7554-3/90.KES150.(N) (617213), 7550-5/85.KES40.(N) (617214), 7551-5/85.KES60.(N) (617215), 7552-5/85.KES80.(N) (617216), 7553-5/85.KES100.(N) (617217), 7554-5/85.KES150.(N) (617218), 7550-5/90.KES40.(N) (617219), 7551-5/90.KES60.(N) (617220), 7552-5/90.KES80.(N) (617221), 7553-5/90.KES100.(N) (617222), 7554-5/90.KES150.(N) (617223), 7561-3/85.KES60.RW.(N) (617231), 7562-3/85.KES80.RW.(N) (617232), 7563-3/85.KES100.RW.(N) (617233), 7564-3/85.KES150.RW.(N) (617234), 7561-3/90.KES60.RW.(N) (617235), 7562-3/90.KES80.RW.(N) (617236), 7563-3/90.KES100.RW.(N) (617237), 7564-3/90.KES150.RW.(N) (617238), 7573-3/85.KES100.(N) (617239), 7574-3/85.KES150.(N) (617240), 7575-3/85.KES250.(N) (617241), 7576-3/85.KES300.(N) (617242), 7573-3/90.KES100.(N) (617243), 7574-3/90.KES150.(N) (617244), 7575-3/90.KES250.(N) (617245), 7576-3/90.KES300.(N) (617246), 7573-5/85.KES100.(N) (617247), 7574-5/85.KES150.(N) (617248), 7575-5/85.KES250.(N) (617249), 7576-5/85.KES300.(N) (617250), 7573-5/90.KES100.(N) (617251), 7574-5/90.KES150.(N) (617252), 7575-5/90.KES250.(N) (617253), 7576-5/90.KES300.(N) (617254), 7580-5/85.KK40.(N) (617274), 7581-5/85.KK60.(N) (617275), 7582-5/85.KK80.(N) (617276), 7583-5/85.KK100.(N) (617277),



magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

7584-5-85.KK150.(N) (617278), 7580-5/90.KK40.(N) (617279), 7581-5/90.KK60.(N) (617280),
7582-5/90.KK80.(N) (617281), 7583-5/90.KK100.(N) (617282), 7584-5-90.KK150.(N) (617283),
7568-5-90.KK200.(N) (617284), 7585-3/85.KK40.MOTK.(N) (617285), 7586-3/85.KK60.MOTK.(N) (617286),
7587-3/85.KK80.MOTK.(N) (617287), 7588-3/85.KK100.MOTK.(N) (617288), 7585-3/90.KK40.MOTK.(N)
(617290), 7586-3/90.KK60.MOTL.(N) (617291), 7587-3/90.KK80.MOTK.(N) (617292),
7588-3/90.KK100.MOTK.(N) (617293), 7585-5/85.KK40.MOTK.(N) (617296), 7586-5/85.KK60.MOTK.(N)
(617297), 7587-5/85.KK80.MOTK.(N) (617298), 7588-5/85.KK100.MOTK.(N) (617299), 7589-5/85.KK150.MOTK
(617300), 7585-5/90.KK40.MOTK.(N) (617301), 7586-5/90.KK60.MOTK.(N) (617302), 7587-5/90.KK80.MOTK.(N)
(617303), 7588-5/90.KK100.MOTK.(N) (617304), 7589-5-90.KK150.MOTK (617305), 7569-5/90.KK200.MOTK
(617306), 7754-5/85.KES150 (JUN754585), 7754-5/90.KES150 (JUN754590), 7550-3 (JUN75503), 7551-3
(JUN75513), 7552-3 (JUN75523), 7553-3 (JUN75533), 7554-3 (JUN75543), 7568-3 (JUN75683), 7568-5.KK200
(JUN75685), 7568-5/85.KK200.(N) (JUN7568585), 7569-3/85.KK200.MOTK.(N) (JUN7569385),
7569-3/90.KK200.MOTK.(N) (JUN7569390), 7569-5/85.KK200.MOTK (JUN7569585), 7573-2 (JUN75732), 7573-3
(JUN75733), 7574-2 (JUN75742), 7574-3 (JUN75743), 7575-2 (JUN75752), 7575-3 (JUN75753), 7576-2
(JUN75762), 7576-3 (JUN75763), 7577-3 (JUN75773), 7580-3 (JUN75803), 7581-3 (JUN75813), 7582-3
(JUN75823), 7583-3 (JUN75833), 7584-3 (JUN75843), 7589-3/85.KK150.MOTK.(N) (JUN7589385),
7589-3/90.KK150.MOTK.(N) (JUN7589390), 7750-3 (JUN77503), 7750-3/85.KES40 (JUN7750385),
7750-3/90.KES40 (JUN7750390), 7750-5/85.KES40.(N) (JUN7750585), 7750-5/90.KES40.(N) (JUN7750590),
7751-3 (JUN77513), 7751-3/90.KES60 (JUN7751390), 7751-5/85.KES60 (JUN7751585), 7751-5/90.KES60
(JUN7751590), 7752-3 (JUN77523), 7752-3/85.KES80 (JUN7752385), 7752-3/90.KES80 (JUN7752390),
7752-5/85.KES80 (JUN7752585), 7752-5/90.KES80 (JUN7752590), 7753-3 (JUN77533), 7753-3/85.KES100
(JUN7753385), 7753-3/90.KES100 (JUN7753390), 7753-5/85.KES100 (JUN7753585), 7753-5/90.KES100
(JUN7753590), 7754-3 (JUN77543), 7754-3/85.KES150 (JUN7754385), 7754-3/90.KES150 (JUN7754390), 7768-3
(JUN77683), 7768-5.KK200 (JUN77685), 7768-5/85.KK200.(N) (JUN7768585), 7768-5/90.KK200.(N)
(JUN7768590), 7769-3/85.KK200.MOTK.(N) (JUN7769385), 7769-3/90.KK200.MOTK.(N) (JUN7769390),
7769-5/85.KK200.MOTK (JUN7769585), 7769-5/90.KK200.MOTK (JUN7769590), 7773-2 (JUN77732), 7773-3
(JUN77733), 7773-3/85.KES100 (JUN7773385), 7773-3/90.KES100 (JUN7773390), 7773-5 (JUN77735),
7773-5/85.KES100.(N) (JUN7773585), 7773-5/90.KES100.(N) (JUN7773590), 7774-2 (JUN77742), 7774-3
(JUN77743), 7774-3/85.KES150 (JUN7774385), 7774-3/90.KES150 (JUN7774390), 7774-5 (JUN77745),
7774-5/85.KES150.(N) (JUN7774585), 7774-5/90.KES150.(N) (JUN7774590), 7775-2 (JUN77752), 7775-3
(JUN77753), 7775-3/85.KES250 (JUN7775385), 7775-3/90.KES250 (JUN7775390), 7775-5 (JUN77755),
7775-5/85.KES250.(N) (JUN7775585), 7775-5/90.KES250.(N) (JUN7775590), 7776-2 (JUN77762), 7776-3
(JUN77763), 7776-3/85.KES300 (JUN7776385), 7776-3/90.KES300 (JUN7776390), 7776-5 (JUN77765),
7776-5/85.KES300.(N) (JUN7776585), 7776-5/90.KES300.(N) (JUN7776590), 7780-3 (JUN77803),
7780-5/85.KK40.(N) (JUN7780585), 7780-5/90.KK40.(N) (JUN7780590), 7781-3 (JUN77813), 7781-5/85.KK60.(N)
(JUN7781585), 7781-5/90.KK60.(N) (JUN7781590), 7782-3 (JUN77823), 7782-5/85.KK80.(N) (JUN7782585),
7782-5/90.KK80.(N) (JUN7782590), 7783-3 (JUN77833), 7783-5/85.KK100.(N) (JUN7783585),
7783-5/90.KK100.(N) (JUN7783590), 7784-3 (JUN77843), 7784-5.KK150 (JUN77845), 7784-5/85.KK150.(N)
(JUN7784585), 7784-5/90.KK150.(N) (JUN7784590), 7785-3/85.KK40.MOTK.(N) (JUN7785385),

magazin online HORECA

Piese schimb / Accesorii / Consumabile / Reparații
Automatizări / Materiale Electrice

7785-3/90.KK40.MOTK.(N) (JUN7785390), 7785-5/85.KK40.MOTK (JUN7785585), 7785-5/90.KK40.MOTK (JUN7785590), 7786-3/85.KK60.MOTK.(N) (JUN7786385), 7786-3/90.KK60.MOTK.(N) (JUN7786390), 7786-5/85.KK60.MOTK (JUN7786585), 7786-5/90.KK60.MOTK (JUN7786590), 7787-3/85.KK80.MOTK.(N) (JUN7787385), 7787-3/90.KK80.MOTK.(N) (JUN7787390), 7787-5/85.KK80.MOTK (JUN7787585), 7787-5/90.KK80.MOTK (JUN7787590), 7788-3/85.KK100.MOTK.(N) (JUN7788385), 7788-3/90.KK100.MOTK.(N) (JUN7788390), 7788-5/85.KK100.MOTK (JUN7788585), 7788-5/90.KK100.MOTK (JUN7788590), 7789-3/85.KK150.MOTK.(N) (JUN7789385), 7789-3/90.KK150.MOTK.(N) (JUN7789390), 7789-5/85.KK150.MOTK (JUN7789585), 7789-5/90.KK150.MOTK (JUN7789590)

